







# Kerstin




1


2


3





1	1X
2	1X
3	1X


<b>A</b>	M6*12
	4X

<b>B</b>	M6*20
	4X

<b>C</b>	Ø18*Ø6.5*1.5
	4X


<b>D</b>	M4*20
	4X

<b>E</b>	
	2X

<b>F</b>	4mm
	1X


I.

1.




A	M6*12	4X
D	M4*20	4X
E		2X
F	4mm	1X

2.



B	M6*20	4X
C	Ø18*Ø6.5*1.5	4X
F	4mm	1X

3.



F	4mm	1X

